

PARTS LIST


PARTS LIST					
Name	Part	Qty	Name	part	Qty
A Castor	8	5	H back frame		1
B base		1	I finishing cover		1
C gas lift		1	J screw M8x30mm		12
D sest and mechanism		1	K shim 8x22x1.5mm		12
E arm rest		2	L spanner 5mm		1
			M spanner 4mm		1
back		1	O spanner 3mm		1
G main lumbar frame		1	N head rest		1




take out two screws on part "G".




insert"H"part into"G"then assemble two screws back and tweak tightly.




connect"F"and"G"according to the picture.




put"K"under"J",insert both of them into holes and tweak tightly



put"I"part upon"G"part,press until tight




according to the picture, use screws to connect mechanism and back frame.



Loose out two wheels from the steel sheets, then insert "E" under the steel sheets, tighten the wheel.



Loose out the screws at the two side of "N"



Put"N"to"F"at the right position then tighten the two screws.