



RUBICO 100



COATING MATERIALS TABLE

| Code     | Name of the cover                       | Composition                                                                           |
|----------|-----------------------------------------|---------------------------------------------------------------------------------------|
| AL       | Alchimia                                | 100% polyester                                                                        |
| BO       | Bloom                                   | 85% polyvinylchloride, 15% polyuretane                                                |
| BN       | Bondai                                  | 100% polyester                                                                        |
| CU       | Cura                                    | 98% recyled polyester, 2% polyester                                                   |
| D        | Dora                                    | 100% polyester                                                                        |
| F/FH     | Fame / Fame Hybrid                      | 95% New Zealand wool, 5% polyamide                                                    |
| FO       | Four                                    | 100% Polyolefin                                                                       |
| NK       | Kortexin                                | 100% polyester, coated with PVC on the reverse side wint water repellent finish (W/R) |
| M        | Meditap                                 | 100% Polyvinyl chloride - resistance to disinfection and sterilization                |
| MT       | Milton                                  | 97% PES, 3% NY                                                                        |
| P        | Leather                                 | genuine bovine leather                                                                |
| RF/RFM   | Relife F.R. + Melange F.R.              | 100% post-consumer Recycled Polyester (75% Melange) + fire resistance                 |
| SK       | Skai                                    | warp 100% polyester, surface 100% polyvinyl chloride                                  |
| S        | Stax                                    | 100% recycled polyester                                                               |
| VIS/VIM  | Visual F.R./ Melange F.R.               | 100% polyester + fire resistance                                                      |
| W        | Wool                                    | 100% wool                                                                             |
| X        | X-Treme                                 | 100% Xtreme FR <sup>®</sup> , fire resistance M1                                      |
| 2        | Silhouette                              | 100% nylon with anti-stain finish                                                     |
| NET EPIC | EPIC                                    | 30% polyester, 70% elastomerized polyamid                                             |
| -        | Eclipse NET mesh                        | 100% polyester, fire resistance TB117 - 2013                                          |
| -        | Oklahoma, Tennessee, Above, Spider mesh | 100% polyester                                                                        |
| -        | Ergosit mesh                            | 100% polyester                                                                        |
| -        | GALA NET mesh                           | 100% polyester                                                                        |

MAINTENANCE

Maintenance of upholstery is carried out by wiping off dirt and spots with a damp cloth; in case of leather or leatherette please use a slightly watery cloth.

The armchair is primarily designed for residential and commercial places. Warranty period is 60 months. During the warranty period, the manufacturer will replace free of charge all parts that have been damaged due to material defects or manufacturing errors. In these cases, the manufacturer replaces defective parts, not the entire armchair.

The warranty does not cover damages caused by:

- 1. Transportation (damages are the responsibility of the carrier)
- 2. Natural disasters
- 3. Incorrect assembly
- 4. Careless and inappropriate use
- 5. Non-compliance with the provided instructions

Glides are fitted with a rectifying scw and its rotation can compensate for floor irregulaties within the rage of 0-10 mm.

